



2117 Safety Guidance



Using the Concrete Screed & Vibrating Poker

- Wear your protective equipment including ear defenders, dust mask, goggles and safety wellington boots.
- Do not use a machine with any guard or safety device removed or disconnected.
- Stop the engine before making any adjustments.
- Watch out for signs that vibration may be affecting your hands, if your fingers start to tingle or feel numb, take a short break from using the machine. Exercise your fingers to encourage blood circulation.
- To help prevent vibration affecting your hands, operate the machine for shorter periods, share the job with a work mate. Keep your hands warm - wearing gloves may
- Stop the engine if leaving the machine unattended.
- You must clean these machines as soon as you have finished work before the concrete mix goes hard.
- If your equipment does not work properly, do not attempt to repair it. Contact the hire company.

Please keep this leaflet safely as it may be required for future reference







2450 Regents Court











©Copyright Hire Association Europe April 2011

Any unauthorised reproduction – manually or electronically – is STRICTLY prohibited

confact the hire company. is found damaged, do not use it equipment on your machines. If anything 1. Check the engines, and all the

cause damage to the surface and the surface while it is still vibrating. It will 2. Do not lay the vibrating poker on a hard

before you start the machines you must

e. Find out now to switch each engine off,

know how to stop them.

vibration could be dangerous. poker while it is in operation, the severe 4. Do not touch the vibrating part of the

keep your nands warm while you are petore you start work, and wear gloves to be hazardous. Warm your hands up 3. Vibration from using these machines can

screed machine.

to move. Get help especially with the These machines are heavy and awkward

SCREED AND POKER

protective equipment

also need to wear appropriate personal e wuxbody who is working near to you will

coming into contact with your bare skin. and full trousers to prevent the mixes 2. You should wear gloves, long sleeves

have to stand in wet concrete. (EN345 or BS1870 / 4972). You may 4. You must wear safety wellington boots

protection for this level as a minimum. ear muffs or plugs giving hearing levels up to 100dB(A) - wear appropriate 3. This equipment is likely to cause noise

you are working with this equipment. (ENJee - B or BS2092 grade 1) when 2. You must wear impact resistant goggles

Concrete Screed & Vibrating Poker

The rules and procedures in force where people are at work may require the person responsible for this equipment to carry out a specific risk assessment.

It is important to read all of this leaflet BEFORE you use the Concrete Screed & Vibrating Poker

- Plan the use of the Concrete Screed and Vibrating Poker so that it can always be used safely.
- Cement mixers are harmful to eyes, lungs and skin. Follow any instructions given by the manufacturers of these cement
- Screed machines are designed to produce a flat smooth finish to large areas of freshly laid concrete. The vibrating action reduces the amount of air trapped near the surface of the concrete.
- The vibrating poker is designed to reduce the amount of air trapped at greater depths in the concrete. This also allows the concrete to flow into every small space and makes the concrete stronger when set.
- The action of these machines, including the vibration, can cause injury or damage if they are not used in a careful and controlled way.
- If you have not used either a screed or a poker before, familiarise yourself with how the machines work before you start on the main task.
- You must have at least the following items of personal protective equipment: impact resistant goggles: EN166 - B or BS2092 grade 1; ear muffs or plugs giving protection for levels up to 100dB(A); Safety wellington boots to EN345 or BS1870/4972; gloves;
- This machine must not be used by minors, or by anyone under the influence of drugs or alcohol.
- This equipment is designed for operation by an able bodied adult. Anyone with either temporary or permanent disability must seek expert advice before using it.













effort has been made by HAE/EHA to ensure that the information given in this docum is accurate and not misleading. HAE/EHA cannot accept responsibility for any loss or liability perceived to have arisen from the use of any such document/material. Only Acts of Parliament and Statutory Instruments have the force of law and only the courts can authoritatively interpret the law.

44 (0) 121 380 4600 44 (0) 121 333 4109

BAY 788 Iludilos The Crescent Birmingham Business Park nuo sinegen uce



level of protection. or environments may require a nigner you use these machines. Particular jobs

minimum that should be worn whenever brotective equipment (ppe) are the 1. The following items of personal

OPERATORS

seek medical advice.

not further contact. If the rash persists, 4. Mild dermatitis will heal providing there is

der any type or cement mix in them. your eyes and seek medical advice if you skin immediately. Thoroughly rinse out 3. Wash cement or plaster mixes off your

was in contact with the skin. rash occurs only where the substance usually itchy and causes flaky skin. The substances. The rash can vary but it is occur when the skin reacts to certain 2. Contact dermatitis is a rash that may

cause contact dermatitis. 1. Wet cement mix is a substance that can

DERMATITIS CEMENT MIXES AND CONTACT

but barriers around your work area. wet cement. Warn others to keep away, 4. Protect other people from the noise and

and that no-one is near to you or could 3. Make sure that the area is clear and safe

orner confined areas.

have proper ventilation when working in pave good ventilation. Ensure that you run these machines indoors unless you injury from breathing toxic fumes, do not To reduce the risk of serious or fatal

fumes from petrol, or gas cylinders. is a danger of explosion. They will ignite Do not use these machines where there

WORK AREA













