



Redistributed under licence from HAE by Banner Plant Limited. Licence expires on 31/05/2025

TURNING OFF THE GAS TORCH

- 1. To turn off the gas torch for a short while, turn off the valve on the gas torch.
2. When you have finished work, turn off the gas torch completely, then close the valve on the cylinder.

CHANGING THE GAS CYLINDER

- 1. Do not smoke while changing the cylinder.
2. Turn the gas torch off and close the valve on the cylinder.
3. Make sure that there are no naked flames nearby.
4. Disconnect the regulator from the cylinder.
5. Remove the plastic protective plug from the valve on the new cylinder.
6. Check that the valve connection on the new cylinder is the same as the one on the old cylinder.
7. If the valve connections are the same fit the new cylinder.
8. Position the new cylinder to the side of the gas torch where it will be clear of the heat, but without straining the gas hose.
9. If you suspect that the cylinder connection is not gas tight, do not try to light the gas torch.

- 10. Ensure the valve is closed on the empty cylinder; re-fit the plastic protective plug, and then move the empty cylinder to a safe location.

USING THE GAS TORCH

- 1. Wear your protective equipment including facemask and goggles.
2. If your equipment is likely to produce toxic fumes, you must wear your facemask; keep others away from the fumes.
3. Do not point the flame at people.
4. Do not direct the flame on to glass; it will crack.
5. Extinguish the flame when you stop work and lay your equipment down.
6. After use, the nozzle will be hot.
7. Remember material you have worked on will remain hot for some time.
8. Extinguish the flame before you put the equipment down.
9. If your equipment does not work properly do not attempt to repair it.

Please keep this leaflet safely as it may be required for future reference



Hire Association Europe
2450 Regents Court
The Crescent
Birmingham Business Park
Solithull B37 7YE

Telephone: 44 (0) 121 380 4600
Fax: 44 (0) 121 333 4109
Email: mail@hae.org.uk
website: www.hae.org.uk

Copyright Hire Association Europe April 2011


Any unauthorised reproduction - manually or electronically - is STRICTLY prohibited

Gas Torch

The rules and procedures in force where people are at work may require the person responsible for this equipment to carry out a specific risk assessment.

It is important to read all of this leaflet BEFORE using the Gas Torch

- 1. Propane gas is extremely flammable. Take care not to cause a fire or explosion.
2. Equipment producing jets of flame can be hazardous if misused.
3. Do not use a gas torch to strip paint; it is too hot and will burn the wood.
4. Pay attention to what is caught in the flame; some substances may produce toxic fumes when burnt.
5. Do not try to use this gas torch to provide general space heating.
6. You must have adequate ventilation to disperse the exhaust fumes from the gas torch.
7. Keep non-essential people, especially children away from the work area.
8. Wear your protective equipment especially eye protection and face mask.
9. Read and follow the safety labels attached to the equipment, they are there to warn of hazards.
10. Do not indulge in any horseplay or irresponsible behaviour while using or working near the gas torch.
11. Do not point the jet of flame at people or animals; you may cause serious burn injuries.
12. After use, the nozzle will be hot. Do not touch it or lay it down on flammable material.
13. A suitable fire extinguisher should be kept nearby while using the gas torch.
14. The heavy gas cylinder used by this equipment can be awkward to move.
15. This equipment must not be used by minors, or by anyone under the influence of drugs or alcohol.
16. This equipment is designed for operation by an able bodied adult.



Every effort has been made by HAE/EHA to ensure that the information given in this document and supporting material is accurate and not misleading. HAE/EHA cannot accept responsibility for any loss or liability perceived to have arisen from the use of any such document/material.

Hire Association Europe
2450 Regents Court
The Crescent
Birmingham Business Park
Solithull B37 7YE

Telephone: 44 (0) 121 380 4600
Fax: 44 (0) 121 333 4109
Email: mail@hae.org.uk
website: www.hae.org.uk

- 1. Ensure that the gas control valve on the gas torch is in the 'OFF' position.
2. Check the gas torch in a safe position and hold that there is nothing near that could catch fire.
3. Open the valve on the gas cylinder.
4. Hold a lighted taper by the nozzle and open the valve on the gas torch.
5. If the gas torch does not light within 10 to 15 seconds turn off the valve on the gas torch. Wait 15 or 20 seconds for the accumulated gas to disperse then attempt to relight the torch.
6. If the gas torch is being lit for the first time since the gas cylinder valve was opened, you may need to hold the lighted taper for a few seconds before the gas ignites.

LIGHTING THE GAS TORCH

- 1. Check your equipment, including the hose and regulator.
2. Before starting, ensure all hose connections are tight.
3. Make sure you understand how the equipment works - before you light the gas torch, you must know how to turn it off.

GAS TORCH

- 1. You will need to wear an appropriate facemask when you are doing work that creates fumes.
2. You must wear goggles when you are working with this equipment.
3. You should wear safety boots when handling heavy cylinders.
4. Anybody who is working near to you will also need to wear appropriate personal protective equipment.

- 1. The following items of personal protective equipment (PPE) are the minimum that should be worn whenever you use a gas torch.
2. This equipment should not be used inside a residential building that is currently occupied.
3. To reduce the risk of serious or fatal injury from breathing toxic fumes that may be given off by certain substances when heated by this gas torch, do not use this equipment inside a building unless it is well ventilated.
4. If propane has been inhaled, and the victim is unconscious, do not attempt rescue. Call the emergency services.
5. Make sure that your work area is clear and safe and that no-one is near to you or could distract you.
6. Protect other people from the danger. Warn others to keep away. Put up a temporary barrier.
7. A suitable fire extinguisher should be kept nearby while using the gas torch.

WORK AREA



Before Starting Work...



PERSONAL PROTECTIVE EQUIPMENT
You should wear the following items of personal protective equipment: Goggles; Facemask; Wear safety boots when handling heavy cylinders; Gloves.

PROPANE GAS SAFETY

1. Users of propane must be prepared for emergency action in case of a serious accident occurring.